

CONTENTS

PREFACE	vii
----------------	-----

CHAPTER A

Accuracy (definition)	1
Activation energy (definition and properties)	1
Activator	2
Adirovitch model	3
Afterglow	7
Aluminium oxide (Al_2O_3)	7
Annealing (definition)	8
Annealing (general considerations)	9
Annealing procedures	10
Anomalous fading	18
Anomalous thermal fading	18
Area measurement methods (generality)	18
Area measurement method (Maxia et al.)	19
Area measurement methods (May and Partridge: general order)	22
Area measurement methods (Muntoni et al.: general order)	22
Area measurement method (Moharil: general order)	23
Area measurement method (Moharil: general order, $s = s(T)$)	24
Area measurement method (Rasheedy: general order)	28
Arrhenius equation	31
Assessment of random uncertainties in precision of TL measurements (general)	32
Atomic number (calculation)	35

CHAPTER B

Basic equation of radiation dosimetry by thermoluminescence	39
Batch of TLDs	41
Braunlich-Scharman model	41

CHAPTER C

Calcium fluoride (CaF_2)	51
Calibration factor F_c (definition)	51
Calibration factor F_c (procedures)	52
Calibration procedure for a batch of TLDs	54
Competition	55

Competitors	57
Computerised glow curve deconvolution (CGCD): Kitis' expressions	57
Condition at the maximum (first order)	65
Condition at the maximum (first order): remarks	66
Condition at the maximum (general order)	66
Condition at the maximum (second order)	68
Condition at the maximum when $s' = s'(T)$ (second-order kinetics)	69
Condition at the maximum when $s'' = s''(T)$ (general-order kinetics)	70
Condition at the maximum when $s = s(T)$ (first-order kinetics)	72
Considerations on the heating rate	73
Considerations on the methods for determining E	79
Considerations on the symmetry factor, μ , and the order of kinetics, b	84
Correction factor for the beam quality, F_{en} (general)	88
Curve fitting method (Kirsh: general order)	90
CVD diamond	91

CHAPTER D

Defects	93
Delocalized bands	97
Determination of the dose by thermoluminescence	97
Dihalides phosphors	98
Dosimeter's background or zero dose reading (definition)	98
Dosimeter's background or zero dose reading (procedure)	99
Dosimetric peak	99
Dosimetric trap	99

CHAPTER E

Effect of temperature lag on trapping parameters	101
Energy dependence (procedure)	102
Environmental dose rate (calculation)	104
Environmental dose rate (correction factors)	107
Erasing treatment	109
Error sources in TLD measurements	109
Exponential heating function (EHF)	112

CHAPTER F

Fading (theoretical aspects)	121
Fading factor	132
A fading based method for checking the presence of closely overlapping peaks in thermoluminescent (TL) materials	133

Fading: useful expressions	137
First-order kinetics when $s = s(T)$	145
Fluorescence	146
Fluorapatite ($\text{Ca}_5\text{F}(\text{PO}_4)_3$)	146
Frequency factor, s	147
Frequency factor, s (errors in its determination)	148
Frequency factor and pre-exponential factor expressions	149

CHAPTER G

Garlick-Gibson model (second-order kinetics)	153
General characteristics of first and second order glow-peaks	155
General-order kinetics when $s'' = s''(T)$	158
Geometrical characteristics of a single peak	159
Glow curve	166
Glow peak parameters	167

CHAPTER H

Heating rate effects	173
Heating rate effects on thermoluminescence of $\text{BaSO}_4:\text{Eu}+\text{PTFE}$	175

CHAPTER I

In-vivo dosimetry (dose calibration factors)	185
Inflection points method (Land: first order)	186
Inflection points method (Singh et al.: general order)	187
Initial rise method	190
Initial rise method when $s = s(T)$ (Aramu et al.)	191
Initialisation procedure	192
Integral approximation	194
Integral approximation when $s = s(T)$	195
Interactive traps	195
Isothermal decay method (Garlick-Gibson: first order)	195
Isothermal decay method (general)	197
Isothermal decay method (May-Partridge: (a) general order)	197
Isothermal decay method (May and Partridge: (b) general order)	198
Isothermal decay method (Moharil: general order)	199
Isothermal decay method (Takeuchi et al.: general order)	200
Isothermal decay method: a new approach	201

CHAPTER K

Keating method (first-order, $s = s(T)$)	207
Killer centres	209
Kinetic parameters determination: observations	209
Kinetics order: effects on the glow-curve shape	214

CHAPTER L

Light transmission of semi-transparent dosimeter	217
Linearisation factor, F_{lin} (general requirements for linearity)	217
Linearity (procedure)	220
Linearity test (procedure)	222
Lithium borate ($\text{Li}_2\text{B}_4\text{O}_7$)	224
Lithium fluoride family (LiF)	225
Localized energy levels	229
Lower detection limit (D_{lat})	229
Luminescence (general)	229
Luminescence (thermal stimulation)	230
Luminescence centres	231
Luminescence dosimetric techniques	231
Luminescence dosimetry	232
Luminescence efficiency	232
Luminescence phenomena	233

CHAPTER M

Magnesium borate ($\text{MgO} \times n\text{B}_2\text{O}_3$)	235
Magnesium fluoride (MgF_2)	236
Magnesium orthosilicate (Mg_2SiO_4)	236
May-Partridge model (general order kinetics)	237
McKeever method	239
Mean and half-life of a trap	240
Metastable state	242
Method based on the temperature at the maximum (Randall-Wilkins)	243
Method based on the temperature at the maximum (Urbach)	244
Methods for checking the linearity	244
Model of non-ideal heat transfer in TL measurements	247
Multi-hit or multi-stage reaction models	249

CHAPTER N

Non linearity	251
Non-ideal heat transfer in TL measurements (generality)	257

Numerical curve fitting method (Mohan-Chen: first order)	258
Numerical curve fitting methods (Mohan-Chen: second order)	260
Numerical curve fitting method (Shenker-Chen: general order)	261

CHAPTER O

Optical bleaching	263
Optical fading	263
Oven (quality control)	263
Observations on the peak-shape methods based on the peak temperature at the maximum	269

CHAPTER P-1

Partridge-May model (zero-order kinetics)	279
Peak-shape method (Balarin: first- and second-order kinetics)	280
Peak shape method (Chen: first- and second-order)	283
Peak shape method (Chen: general-order kinetics)	294
Peak shape method (Christodoulides: first- and general-order)	297
Peak shape method (Gartia, Singh & Mazumdar: (b) general order)	300
Peak shape method (Grossweiner: first order)	301
Peak shape method (Halperin-Braner)	302
Peak shape method (Lushchik: first and second order)	312
Peak shape method (Mazumdar, Singh & Gartia: (a) general order)	315
Peak shape method (parameters)	318
Peak-shape methods based on the peak temperature at the maximum	319
Peak shape method when $s = s(T)$. (Chen: first-, second- and general-order)	322
Peak shape method: reliability expressions	331

CHAPTER P-2

Peak shift	341
Peak shift as a function of dose	343
Peak singularity	352
Perovskite's family (ABX_3)	354
Phosphorescence	355
Phosphors (definition)	358
Photon energy response (calculation)	358
Photon energy response (definition)	361
Phototransferred thermoluminescence (PTTL) (general)	362
Phototransferred thermoluminescence (PTTL): model	363
Post-irradiation annealing	368
Post-readout annealing	368
Precision and accuracy (general considerations)	369

Precision concerning a group of TLDs of the same type submitted to one irradiation	372
Precision concerning only one TLD undergoing repeated cycles of measurements (same dose)	373
Precision concerning several identical dosimeters submitted to different doses	373
Precision concerning several identical dosimeters undergoing repeated and equal irradiation (procedures)	376
Precision in TL measurements (definition)	384
Pre-exponential factor	384
Pre-exponential factor (definition)	402
Pre-irradiation annealing	405
Pre-readout annealing	405
Properties of the maximum conditions	405

CHAPTER Q

Quasiequilibrium condition	407
----------------------------	-----

CHAPTER R

Radiation-induced-defects	409
Randall-Wilkins model (first-order kinetics)	409
Rasheedy modified kinetics equations	413
Reading stability	415
Recombination centre	416
Recombination processes	416
Reference and field dosimeters (definitions)	417
Relative intrinsic sensitivity factor or individual correction factor S_i (definition)	417
Relative intrinsic sensitivity factor or individual correction factor S_i (procedures)	420
Residual TL signal	426
Rubidium halide	426

CHAPTER S

Second-order kinetics when $s' = s'(T)$	429
Self-dose in competition to fading (procedure)	429
Sensitisation (definition)	431
Sensitivity (definition)	431
Sensitivity variations with optical transmission	431
Sensitivity variations with thickness of TLD	432
Set up of a thermoluminescent dosimetric system (general requirements)	433
Simultaneous determination of dose and time elapsed since irradiation	434
Sodium pyrophosphate ($\text{Na}_4\text{P}_2\text{O}_7$)	442
Solid state dosimeters	443
Solid state dosimetry	443

Spurious thermoluminescence: chemiluminescence	443
Spurious thermoluminescence: surface-related phenomena	443
Spurious thermoluminescence: triboluminescence	444
Stability factor F_{st} (definition)	444
Stability factor F_{st} (procedure)	444
Stability of the reading system background	447
Stability of the reading system background (procedure)	447
Stability of the TL response	447
Standard annealing	448
Stokes' law	449
Sulphate phosphors	449

CHAPTER T

Temperature gradient in a TL sample	451
Temperature lag: Kitis' expressions for correction (procedure)	453
Temperature lag: Kitis' expressions for correction (theory)	455
Temperature ratios T_1/T_M and T_2/T_M as a function of the kinetics order b	460
Theory of thermoluminescent dose measurement	463
Test for batch homogeneity	468
Test for the reproducibility of a TL system (procedure)	472
Thermal cleaning (peak separation)	474
Thermal fading (procedure)	475
Thermal quenching	477
Thermally connected traps	477
Thermally disconnected traps	478
Thermoluminescence (thermodynamic definition)	478
Thermoluminescence (TL)	480
Thermoluminescent dosimetric system (definition)	480
Thermoluminescent materials: requirements	481
Three points method	482
Tissue equivalent phosphors	486
Trap characteristics obtained by fading experiments	487
Trap creation model	488
Trapping state	489
Tunnelling	489
Two-trap model (Sweet and Urquhart)	490

CHAPTER V

Various heating rates method (Bohum, Porfianovitch, Booth: first order)	493
Various heating rates method (Chen-Winer: first order)	493
Various heating rates method (Chen-Winer: second and general orders)	494

Various heating rates method (Gartia et al.: general order)	496
Various heating rates method (Hoogenstraaten: first order)	497
Various heating rates method (Rasheedy)	497
Various heating rates method (Sweet-Urquhart: two trap model)	500
Various heating rate method when $s = s(T)$ (Chen and Winer: first- and general-order)	501

CHAPTER Z

Zirconium Oxide (ZrO ₂)	505
-------------------------------------	-----

APPENDIX 1

Appendix b=1	507
Appendix b=1.1	509
Appendix b=1.2	511
Appendix b=1.3	513
Appendix b=1.4	515
Appendix b=1.5	517
Appendix b=1.6	519
Appendix b=1.7	521
Appendix b=1.8	523
Appendix b=1.9	525
Appendix b=2	527

APPENDIX 2

APPENDIX 3

SUBJECT INDEX

ABOUT THE AUTHOR