

# Contents

Preface	v
<b>Chapter 1 Ore Minerals</b>	<b>1</b>
1.1. Types of Ore Mineral . . . . .	1
1.2. Types of Crystal Lattice . . . . .	1
1.2.1. Introduction . . . . .	1
1.2.2. Silicate Structures . . . . .	4
1.2.3. Oxides . . . . .	6
1.2.4. Sulphides . . . . .	12
<b>Chapter 2 Equilibrium in Aqueous Solutions</b>	<b>15</b>
2.1. Introduction . . . . .	15
2.2. Ionic Activities . . . . .	20
2.2.1. Debye–Hückel Theory . . . . .	20
2.2.2. Extension to More Concentrated Solutions . . . . .	25
2.2.3. Extension to Mixed Electrolyte Solutions . . . . .	27
2.2.4. Application of Pitzer’s Equations; Some Worked Examples . . . . .	37
2.3. Metal Complex Formation and Equilibrium Constants . . . . .	50
2.3.1. Complex Formation . . . . .	50
2.3.2. Thermodynamics of Equilibrium Constants . . . . .	54
2.3.3. Selection of Values of Equilibrium Constants . . . . .	60
2.4. Complex Formation or Ion Association? . . . . .	62
<b>Chapter 3 Thermodynamics of Reactions</b>	<b>65</b>
3.1. Introduction . . . . .	65
3.2. Standard Free Energies of Formation . . . . .	66

3.3.	Predominance Area Diagram for the Fe–H <sub>2</sub> O System, 298.15 K . . . . .	68
3.3.1.	Reactions Involving Dissolved Species and Solids, Nonredox . . . . .	68
3.3.2.	Reactions Involving Oxidation and Reduction . . . . .	71
3.3.3.	The Hydrogen Scale . . . . .	73
3.3.4.	The pe Scale . . . . .	74
3.3.5.	Equilibria between Solids . . . . .	76
3.3.6.	Equilibria between Ions and Solids . . . . .	79
3.3.7.	Equilibria between Ions . . . . .	80
3.3.8.	Representation of Equilibria . . . . .	80
3.3.9.	Discussion of the Diagram, Fig. 3.1 . . . . .	83
3.4.	The Sulphur–Water System, 298.15 K . . . . .	84
3.4.1.	Data Used . . . . .	84
3.4.2.	Acid Dissociation Constants . . . . .	85
3.4.3.	Redox Equilibria . . . . .	85
3.4.4.	Discussion of the Diagram, Fig. 3.2 . . . . .	86
3.5.	The Copper–Sulphur–Water System, 298.15 K . . . . .	88
3.5.1.	Data Used . . . . .	88
3.5.2.	Equilibria . . . . .	88
3.5.3.	Discussion of the Diagram, Fig. 3.3 . . . . .	90
3.6.	Thermodynamics of Electrolyte Solutions at Elevated Temperatures . . . . .	92
3.6.1.	Construction of Predominance Area Diagrams for Elevated Temperatures . . . . .	92
3.6.2.	The S–H <sub>2</sub> O System, 423 K . . . . .	94
3.6.3.	The Cu–S–H <sub>2</sub> O System, 423 K . . . . .	97
3.6.4.	The Fe–S–H <sub>2</sub> O System, 423 K . . . . .	104
3.6.5.	Estimation of Entropies and Heat Capacities of Ionic Species . . . . .	105
3.7.	Precipitation of Metals from Solution by Reduction . . . . .	109
3.7.1.	Introduction . . . . .	109
3.7.2.	Deposition of Metals by Electrolysis . . . . .	110
3.7.3.	Precipitation of Metals by Hydrogen Gas . . . . .	112
3.8.	Precipitation of Compounds from Solution . . . . .	119
3.8.1.	Introduction . . . . .	119
3.8.2.	The Second Dissociation Constant of H <sub>2</sub> S(aq) . . . . .	120
3.8.3.	Precipitation of Sparingly Soluble Metal Sulphides . . . . .	122

3.8.4. Nucleation and Crystal Growth . . . . .	124
3.8.5. Precipitation of Arsenates . . . . .	129
3.8.6. Precipitation of Iron as Oxides . . . . .	130
3.9. pH at Elevated Temperatures . . . . .	136
3.10. Precipitation of Solids at Elevated Temperatures . . . . .	139
3.10.1. Introduction . . . . .	139
3.10.2. True Solubility and Temperature . . . . .	141
3.10.3. Hydrolysis and Temperature . . . . .	141
3.11. Speciation Diagrams . . . . .	143
3.11.1. Introduction . . . . .	143
3.11.2. Speciation in Multicomponent Solutions . . . . .	146
3.11.3. Precipitation of Trace Metals in Estuarine Water . . . . .	154
3.11.4. Adsorption and Coprecipitation of Metals from Solutions . . . . .	160

## Chapter 4 Kinetics of Heterogeneous Reactions in

### Hydrometallurgy

**165**

4.1. Rate Controlling Processes . . . . .	165
4.1.1. Introduction . . . . .	165
4.1.2. Transport and Chemical Control . . . . .	166
4.1.3. The Nernst Theory for Transport Control . . . . .	167
4.1.4. Hydrodynamic Theory for Transport Control . . . . .	169
4.2. Experimental Methods for Studying Leaching Kinetics . . . . .	174
4.2.1. Introduction . . . . .	174
4.2.2. Use of an Exposed Face of Mounted Solid . . . . .	177
4.2.3. Use of an Exposed Face of a Rotating Disc . . . . .	180
4.2.4. Use of Particulate Solid . . . . .	185
4.2.5. Electrochemical Methods of Following Leaching Reactions Involving Oxidation or Reduction . . . . .	189
4.3. Kinetics of Leaching Ground Ores and Concentrates . . . . .	199
4.3.1. The Problem of Non-uniform Particle Size . . . . .	199
4.3.2. Equations for Modelling Leaching Kinetics . . . . .	200
4.3.3. Calculation of the Rate of Dissolution of Zinc Calcine in Dilute Acid Solutions . . . . .	203
4.4. Kinetics of Reactions in Which Metals are Precipitated from Solutions by Gases . . . . .	205
4.4.1. Introduction . . . . .	205

4.4.2.	Reduction of Nickel Salts in Aqueous Solutions by Hydrogen . . . . .	206
4.4.3.	Reduction of Cobalt Salts in Aqueous Solutions by Hydrogen . . . . .	216
4.4.4.	Reduction of Copper (II) Acetate in Aqueous Solutions by Hydrogen . . . . .	220
4.4.5.	Reduction Reactions between Metal Salts and Carbon Monoxide in Hydrometallurgy . . . . .	232
<b>Chapter 5 Chemistry of Leaching Processes</b>		<b>235</b>
5.1.	Introduction . . . . .	235
5.2.	Leaching of Oxides and Silicates . . . . .	239
5.2.1.	Reactions of Oxides not Involving Oxidation or Reduction . . . . .	239
5.2.2.	Reactions of Oxides Involving Oxidation . . . . .	241
5.2.3.	Electrochemical Model for the Oxidation Leaching of Uranium Dioxide . . . . .	249
5.2.4.	Leaching of Silicates . . . . .	273
5.3.	Leaching of Sulphides . . . . .	279
5.3.1.	Thermodynamics of the Metastable S-H <sub>2</sub> O System . . . . .	279
5.3.2.	Leaching of Iron-Containing Sulphides in Alkaline Solutions . . . . .	282
5.3.3.	Oxidative Leaching of Chalcocite in Acidic Solutions . . . . .	287
5.3.4.	Oxidative Leaching of Bornite in Acidic Solutions . . . . .	310
5.3.5.	Oxidative Leaching of $\alpha$ -Chalcopyrite and Mooihoekite ( $\gamma$ -Chalcopyrite) in Acidic Solutions . . . . .	327
5.3.6.	Diffusion of Cations in Copper-Containing Sulphides . . . . .	379
Appendix		389
References		391
Index		411