

Contents

<i>Preface</i>	vii
<i>Abbreviations</i>	ix
<i>Acknowledgements</i>	xi
1. Introduction to the Actinides	1
1.1 Actinide Series	1
1.1.1 History	1
1.1.2 Basic physical and chemical properties	8
1.1.3 History of using actinide-containing materials	8
1.1.4 High toxicity and long-lived radioactivity	17
1.1.5 Need for actinide immobilisation	19
1.2 Natural Actinides and Minerals	21
1.2.1 Uraninite, pitchblende and thorianite	21
1.2.2 Coffinite and thorite	23
1.2.3 Brannerite	24
1.2.4 Miscellaneous	25
1.3 Artificial Actinides	25
1.3.1 Actinide production in the nuclear fuel cycle	25
1.3.2 Weapons-grade plutonium	29
1.3.3 Minor actinides	33
1.3.3.1 Neptunium-237	33
1.3.3.2 Americium	34

	1.3.3.3	Curium	35
	1.3.3.4	Berkelium and Californium	36
1.4		Actinide Host-Phases	36
	1.4.1	Natural accessory minerals	36
	1.4.2	Zircon and hafnon	38
	1.4.3	Monazite	41
	1.4.4	Zirconolite	41
	1.4.5	Baddeleyite (monoclinic zirconia)	42
	1.4.6	Tazheranite (cubic zirconia)	43
	1.4.7	Xenotime	43
	1.4.8	Apatite	44
	1.4.9	Pyrochlore	45
	1.4.10	Perovskite	46
	1.4.11	Garnet	47
	1.4.12	Murataite	49
	1.4.13	Kosnarite	49
	1.4.14	Natural gels	50
		References	52
2.		Current and Potential Actinide Applications	57
	2.1	Advanced Nuclear Fuel Cycle	57
		2.1.1 MOX nuclear fuel	57
		2.1.2 Ceramic nuclear fuel	58
		2.1.3 Advanced nuclear reactors	59
	2.2	Inert Pu Ceramic Fuel	60
	2.3	Sealed Radioactive Sources	61
	2.4	Self-glowing Materials	65
	2.5	Transmutation Targets	68
	2.6	Summary	69
		References	69
3.		Waste Actinide Immobilisation	73
	3.1	Ceramic Nuclear Wasteforms: Historical Overview	73
		3.1.1 Early work	73
		3.1.2 Emergence of Pu wasteforms	75

3.1.3	Emergence of durability studies	78
3.2	Titanate-based Ceramics	83
3.2.1	Synroc	83
3.2.2	Ti-pyrochlore	84
3.3	Phosphate-based Ceramics	87
3.3.1	Monazite	87
3.3.2	Th-phosphate/diphosphate (TPD)	87
3.3.3	Kosnarite and NZP	88
3.3.4	Apatite	88
3.4	Ceramics Based on Zirconium and Hafnium Minerals	89
3.4.1	Zircon/zirconia and hafnon/hafnia	89
3.4.2	Cubic zirconia (tazheranite) and hafnia	92
3.5	Garnet/perovskite	94
3.6	Summary	100
	References	100
4.	Synthesis Methods	111
4.1	Precursor Fabrication	111
4.1.1	Sol-gel	111
4.1.2	Co-precipitation	115
4.1.3	Oxide powder mix	116
4.2	Hot Uniaxial Pressing (HUP)	117
4.3	Hot Isostatic Pressing (HIP)	118
4.4	Pressing-sintering	118
4.5	Melting-crystallisation	120
4.6	Self-sustaining (Self-propagating) High Temperature Reactions	122
4.7	Single Crystal Growth	123
4.8	Summary	128
	References	129
5.	Examination of Highly Radioactive Samples	133
5.1	XRD Analysis	133
5.2	SEM and EPMA	134
5.3	Cathodoluminescence	139

5.4	Optical Microscopy	142
5.5	Mechanical Durability	143
5.6	Leach and Alteration Tests	145
	References	152
6.	Radiation Damage	157
6.1	Ion-irradiation	164
6.2	Doping with ²³⁸ Pu and ²⁴⁴ Cm	166
6.2.1	Zircon/zirconia and hafnon/hafnia ceramics	166
6.2.2	Zircon single crystal	168
6.2.3	Cubic zirconia ceramic	170
6.2.4	Monazite ceramic	171
6.2.5	Monazite single crystal	172
6.2.6	Ti-pyrochlore ceramic	173
6.2.7	Zr-pyrochlore ceramic	177
6.2.8	Zirconolite ceramic	178
6.2.9	Garnet ceramic	180
6.2.10	Silicate-apatite ceramic and chlorine-apatite powder	180
6.3	Main points from Self-irradiation/radiation Damage Studies	181
	References	181
7.	What is the Future?	189
7.1	Safety Issues	189
7.2	Burning (Transmutation Option)	190
7.3	Disposal of Waste Actinides	190
7.4	Performance of Actinides in Disposal Environment	192
7.5	Conclusions	192
	Index	195